

*Loren -  
 RELEASE MEANS NOT DELIVERED.  
 AND LET ME WORK OUT WITH TOMMY  
 KNOW HOW THEY WILL BE  
 HANDLED. JRS*

LORD NELSON YACHTS  
 VESSEL ORDER FORM

MODEL ORDERED Victory 49' Tug DATE 11/08/86

HULL NUMBER 49-005 SHIPPING DATE FEB 1988

DESTINATION Seattle Washington ARRIVAL DATE FEB 1988

DEPOSIT RECEIVED Yes LETTER OF CREDIT # \_\_\_\_\_

LETTER OF CREDIT PAYABLE TO ADMIRALTY LTD C/O FIRST INTERSTATE BANK  
 OF Washington, PO BOX 160 Seattle Washington 98111

BUYER NAME Cruising Yachts Ltd. PHONE # (206)632 4819

ADDRESS 927 N.Northlake Way CITY Seattle

STATE Washington ZIP 98103

HULL COLOR Roberts Gray#1203 BOOT STRIPE Endeavour Blue 6007

CABIN COLOR Cloud White 1412 TRIM COLOR Endeavour Blue 6007

ADDITIONAL COLORS \_\_\_\_\_

UPHOLSTERY COLORS H-79 Light Blue

ADDITIONAL EQUIPMENT (Yard Installation) 1.Engine to Be 6 Cylinder

Cummins 6BT5.9M Windlass NEILSON V1000 3.Norcold Refrigerator

4. Mast and Boom Steeped aft of stack 5. Install a second saltwater

Washdown on the stern of the boat.Use the same pump as the

forward washdown 5.Install additional 1 inch thruhull in Engine

Room with scoop facing forward. 6. Please wire for two overhead

fans in pilothouse for defrosters.If you have good quality fans

please install. 7. Trash compactor 8.Holding tank 9Westinghouser

Washer/Dryer white in color. 9. 8KW Northern lights Generator

Balmar 40 amp Battery Charger 10. Please wire all cabins for

stereo speakers. 11. Sight gages and cleanout panels on all tanks

*466-1000*

12. If possible put an eyebrow across the aft end of cabin to keep from pouring over the top of the door.

CHANGE REQUESTS (Yard) Subject to approval and price quotation by representative of Admiralty Ltd. Drawings and measurements may be required.

- Provide 3' wide access door through bulkhead at rear of engine room to aft lazarette.
- 2. The bookshelf door from master stateroom to engine room should be one piece instead of two.
- 3. In master stateroom provide doorway into forward cabin on starboard side of bed This will eliminate the seat and make hanging locker smaller
- 4. Install hanging locker in place of seat in forward stateroom
- 5. Install 110 volt outlet at vanity in master stateroom.
- 6. Make hanging locker wider on starboard side of master stateroom
- 7. The galley counter facing saloon should have an 8" overhang.
- 8. Main saloon table to similar to 37 tug. Size to be suitable for settee. Install lockdowns on starboard side as well.
- 9 Install bookshelf aft starboard side of main saloon like 49-02.
- 10. Install full width drawer under pilothouse settee.
- 11. Install flybridge station with railing and controls. No seat
- 12. Install non-skid on side decks instead of teak
- 13. Please supply an extra set of swim ladder pegs. We will mount
- 14. Install 3 additional 110 volt outlets outside as follows  
aft deck , forward deck . on the stack all to have weather proof caps.

ORDER APPROVED BY

*J. Wall*

DATED

12-07-87

NT Rate now

28.61 not

28.57

~~241.69~~  
{241.69}

2. Base Price

184,400

(400 included mast & Boom)

{405.59} {11,600}

3. Base Price

includes Cost of  
installation of Generator

{1153.84} {33,000}

4. 4748.68 diff

14

97

WOUL I

PILOT

STOVE

RATOR

AULIC

very

RA 142

AIR HI

HULL NO. 49' #05

VESSEL: SEIAN (LEYTE NAVIGATION S.A.)

SHIPPING DATE: Feb. 14, 1988

FROM: KEELUNG TO: TACOMA

STANDARD PRICE: 186 979.02

L/C AMOUNT: \_\_\_\_\_

Page 1

184,400  
at 29  
5347600  
5275684  
71916

labor to install op. in Base Cost →

included in Base (400) →

NO.	CHINESE	ENGLISH	QTY.	AMOUNT	OPTIONAL EQUIPMENT
1.	海底漆	ANTIFOULING PAINT	570.41	NT\$ 16,600.	
2.	自動駕駛	AUTOPILOT 6000MK2			
3.	瓦斯爐	GAS STOVE			
4.	發電機	GENERATOR M6000US	5810.13	NT\$ 166,170.	<33,000>
5.	油壓駕駛系統	HYDRAULIC STEERING SYSTEM			standard
27B.		Battery Ch'g	352.34	10,935	
7.	萬向車心	SCATRA 14200			
8.	管熱器	WARM AIR HEATING D3L			
9.	起錨機	WINDLASS WVC1000C	1977.27	NT\$ 56,550.	
10.	桅杆全套	MAST & BOOM (SUBTRACT LIGHT MAST)	405.59	NT\$ 11,600.	<11,600>
11.	桅杆半套	LIGHT MAST			
12.	"L"型客廳沙發	"L" TYPE SOFA			
13.	冰箱門	ICE BOX DOOR			
14.	紗窗全套	WINDOW SCREEN W/FRAME			
15.	白鐵船外梯	SWIMMING LADDER			no charge
16.	拖船柱	MOORING BIT			"
17.	船後沖水頭房屋	DECK SHOWER STERN HOT & COLD			
18.	ISO樹脂	ISO TYPE RESIN UNDER GELCOAT OF HULL			
19.	污水箱全套	S.S. HOLDING TANK WITH PUMP (2 pcs)	1671.32	NT\$ 47,800.	
20.	甲板箱	DECK BOX			
21.	前艙化粧台	VANITY IN FORWARD CABIN			
22.	防撞白鐵條	S.S. RUBER STRIPPING			
23.	前艙"V"型床	"V" BERTH'S IN FORWARD CABIN			
24.		TWO FANS IN PILOTHOUSE	34.96	NT\$ 1,000.	
25.		Provide 3' wide access door through bulkhead at rear of engine room to aft lazarette.	83.91	NT\$ 2,400.	
26.		In master stateroom provide doorway into forward cabin	209.09	NT\$ 5,980.	

VESSEL: \_\_\_\_\_

FROM: \_\_\_\_\_ TO: \_\_\_\_\_

PRICE: \_\_\_\_\_

L/C AMOUNT: \_\_\_\_\_

NO.	CHINESE	ENGLISH	QTY.	AMOUNT	OPTIONAL EQUIPMENT
28.		Flyingbridge Railing	1115.38	NT\$ 31,900.-	
29.		Flyingbridge Pedestal & Guard	524.47	NT\$ 15,000.-	
30.		Dual Hydraulic subtract Single Hydraulic	374.44	NT\$ 10,709.-	
31.		Dual Hydraulic install & Material	404.54	NT\$ 11,570.-	
5.		sub. Total .....		NT\$ 388,214.-	
6.		Base .....		NT\$ 5,347,600.-	
7.		Total .....		NT\$ 5,735,814.- / 28.57	
8.		Please issued T/T or L/C the amount	=US\$	200,763.-	(Feb. 5, 1988)
9.					
10.					
11.		<i>Per Agreement:</i>			
12.		<i>Base: 5,347,600 x 29 = 184,400 (most x 2000)</i>			
13.		<i>5,273,840 28.6 =</i>			
14.		<i>73760 = 2579.</i>			
15.		<i>186,979</i>			
16.					
17.					
18.					
19.					
20.					
21.					
22.					
23.					
24.					
25.					
26.					
27.					